



# $\begin{array}{c} \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{$

1	A	I	0	D	K	П	V	C	Α	D	Λ
- 1	71	<i>ر</i> ۲	u				N	G	$\overline{}$		$\overline{}$

X axis stroke (Table)	mm	2200 - 4600
Y axis stroke (Headstock)	mm	1700 - 3500
Z axis stroke (Column)	mm	2000 - 3200
Swing diameter	mm	2200 - 4600

## **TABLE**

Table or pallet size	mm	1000x1000 - 2000x2500
Load capacity	kg	up to 35000

## **H** HEADSTOCK

Spindle transmission		Direct Drive	
Spindle power (S1)	kW	94	
Spindle torque (S1)	Nm	1793	
Spindle speed	rpm	5000	

## HVA HEADSTOCK

Spindle transmission		Direct Drive	
Spindle power (S1)	kW	74	
Spindle torque (S1)	Nm	609 / 286	
Spindle speed	rpm	8000 / 12500	
A axis contouring torque	Nm	4000	
A axis clamping torque	Nm	8000	

## **M-HD HEADSTOCK**

Spindle transmission		Direct Drive
Spindle power (S1)	kW	55 / 66 / 105
Spindle torque (S1)	Nm	750 / 320 / 1035
Spindle speed	rpm	6000 / 12000 / 6000
A axis contouring torque	Nm	8000
A axis clamping torque	Nm	12000

1/4







# $\begin{array}{c} \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{I} & \mathbf{I} \\ \mathbf{I} & \mathbf{$

## **W** HEADSTOCK

Boring spindle diameter	mm	130 - 160	
W axis stroke (Boring spindle)	mm	800	
Spindle transmission		2 ranges	
Spindle power (S1)	kW	37 - 52	
Spindle torque (S1)	Nm	1530 - 2396	
Spindle speed	rpm	3500 - 4000	

## WD HEADSTOCK

Boring spindle diameter	mm	110 - 160
W axis stroke (Boring spindle)	mm	up to 800
Spindle transmission		Direct Drive
Spindle power (S1)	kW	76 - 78
Spindle torque (S1)	Nm	1500 - 2167
Spindle speed	rpm	4000 - 5000

## **LINEAR AXES FEATURES**

X,Y,Z axes rapid feed	mm/min	up to 50000
B axis rapid feed	rpm	up to 10

2/4







## **WORKING AREA**

X axis stroke (Table)	mm	2200 - 3800
Y axis stroke (Headstock)	mm	1700 - 3000
Z axis stroke (Column)	mm	2000 - 3200
Swing diameter	mm	2200 - 3800

## **TABLE**

Table or pallet size	mm	Ø1250 - Ø2500	
Load capacity	kg	up to 15000	
Turning speed	rpm	up to 350	

## HVA HEADSTOCK

Spindle transmission		Direct Drive	
Spindle power (S1)	kW	74	
Spindle torque (S1)	Nm	609 / 286	
Spindle speed	rpm	8000 / 12500	
A axis contouring torque	Nm	4000	
A axis clamping torque	Nm	8000	

## **M-HD HEADSTOCK**

Spindle transmission		Direct Drive	
Spindle power (S1)	kW	55 / 66 / 105	
Spindle torque (S1)	Nm	750 / 320 / 1035	
Spindle speed	rpm	6000 / 12000 / 6000	
A axis contouring torque	Nm	8000	
A axis clamping torque	Nm	12000	







# 

## **W** HEADSTOCK

Boring spindle diameter	mm	130 - 160
W axis stroke (Boring spindle)	mm	800
Spindle transmission		2 ranges
Spindle power (S1)	kW	37 - 52
Spindle torque (S1)	Nm	1530 - 2396
Spindle speed	rpm	3500 - 4000

## **WD** HEADSTOCK

Boring spindle diameter	mm	110 – 160
W axis stroke (Boring spindle)	mm	up to 800
Spindle transmission		Direct Drive
Spindle power (S1)	kW	76 - 78
Spindle torque (S1)	Nm	1500 - 2167
Spindle speed	rpm	4000 - 5000

## **LINEAR AXES FEATURES**

X,Y,Z axes rapid feed mm/min fino a 50000	
---	--